


09(T)/2015 VIET NAM - NORTH CENTRAL COAST - THANH HOA - NGHI SON - Dredging operation.

Source: Viet Nam Maritime Safety - North Notice No. 242/TBHH-TCTBĐATHH MB
 247/TBHH-TCTBĐATHH MB
 254/TBHH-TCTBĐATHH MB

Marine work are being carried out in the hatched area and marked by points from No. 1 to No. 14 with coordinates listed in the table below.

Chart affected - VN50012, VN40013 (Edition number 1, Edition date April 16th, 2015)




(All positions are referred to WGS84 Datum)

09(T)/2015 VIỆT NAM - BỜ BIỂN BẮC TRUNG BỘ - THANH HÓA - NGHI SƠN - Hoạt động nạo vét.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 242/TBHH-TCTBĐATHH MB
247/TBHH-TCTBĐATHH MB
254/TBHH-TCTBĐATHH MB

Công việc nạo vét sẽ được tiến hành trong khu vực gạch chéo và được đánh dấu bởi các điểm từ 1 đến 14 có tọa độ được liệt kê trong bảng dưới đây.

Hải đồ ảnh hưởng - VN50012, VN40013 (Phiên bản 1, ngày 16 tháng 4 năm 2015)



(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)