

**305(T)/2019 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.**

Source: Viet Nam Maritime Safety - North, Notice No. 419(T)/2019/TBHH-TCTBDATHHMB

The following lateral buoys have been temporarily adjusted position:

<i>Designation</i>	<i>Characteristic</i>	<i>New Position</i>	<i>Old Position</i>
HP32	Fl.R.3s	20°49.02'N 106°53.70'E	20°49.07'N 106°53.59'E
HP34	Fl.R.3s	20°49.12'N 106°53.24'E	20°49.11'N 106°53.35'E

(All positions are referred to WGS84 Datum)

**Chart affected - VN50008**

**305(T)/2019 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Hệ thống phao.**

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 419(T)/2019/TBHH-TCTBDATHHMB

Các phao luồng dưới đây được tạm thời điều chỉnh vị trí:

<i>Tên</i>	<i>Đặc tính</i>	<i>Vị trí mới</i>	<i>Vị trí cũ</i>
HP32	Fl.R.3s	20°49.02'N 106°53.70'E	20°49.07'N 106°53.59'E
HP34	Fl.R.3s	20°49.12'N 106°53.24'E	20°49.11'N 106°53.35'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

**Hải đồ ảnh hưởng - VN50008**