

37(T)/2019 VIET NAM - NORTH EAST COAST - HAI PHONG - AISs.

Source: Viet Nam Maritime Safety - North, Notice No. 50/(T)/2019/TBHH-TCTBDATHH MB

Three Automatic Identification Systems at the following light-buoys are temporarily out of service

Light-buoy	Position
<i>HP7</i>	20°42.38'N, 106°58.98'E
<i>HP13</i>	20°44.48'N, 106°57.35'E
<i>S</i>	20°48.33'N, 106°54.62'E

(All position are referred to WGS84 Datum)

Charts affected - VN50007 - VN50008

37(T)/2019 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Hệ thống nhận dạng tự động.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 50(T)/2019/TBHH-TCTBDATHH MB

Ba hệ thống nhận dạng tự động, *AIS*, lắp trên các phao sau tạm ngừng hoạt động.

Phao	Vị trí
<i>HP7</i>	20°42.38'N, 106°58.98'E
<i>HP13</i>	20°44.48'N, 106°57.35'E
<i>S</i>	20°48.33'N, 106°54.62'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

Các hải đồ ảnh hưởng - VN50007 - VN50008