

99(P)/2019 VIET NAM - SOUTHWEST COAST - CAN THO - Dredged area.

Source: Viet Nam Maritime Safety - South Notice No. 100/TBHH-TCTBĐATHH MN

1. Dredging works are taking place, until 13 September 2019, from beacon 21 (9°37.67'N, 106°26.16'E) to buoy 47 (9°38.56'N, 106°13.87'E).
2. Mariners are advised to navigate with caution in the adjacent areas.
3. Charts will be updated when work is complete.

(All position are referred to WGS84 Datum)

Charts affected - VN50038 - VN50040 - VN50041

99(P)/2019 VIỆT NAM - BỜ BIỂN TÂY NAM BỘ - CẦN THƠ - Khu vực được nạo vét

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Nam, Thông báo số 100/TBHH-TCTBĐATHH MN

1. Công trình nạo vét được thực hiện đến ngày 13 tháng 9 năm 2019, từ đăng tiêu 21 (9°37.67'N, 106°26.16'E) đến phao 47 (9°38.56'N, 106°13.87'E).
2. Người hàng hải được khuyến cáo tăng cường cảnh giới khi đi qua các khu vực gần đây.
3. Các hải đồ sẽ được cập nhật khi công trình hoàn thành.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

Các hải đồ ảnh hưởng - VN50038 - VN50040 - VN50041