

129(P)/2023 VIET NAM - NORTH EAST COAST - HAI PHONG - Dredging area.

Source: Viet Nam Maritime Safety - North Notice No. 314(T)/2023/TBHH-TCTBĐATHH MB

1. Dredging area: Ha Nam, Bach Dang fairway of Hai Phong (from buoy HP29 to buoy S1).
2. Mariners are advised to navigate with caution in the area.
3. Charts will be updated when works are complete.

(All positions are referred to WGS84 Datum)

Chart affected - VN50008

129(P)/2023 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Khu vực nạo vét.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 314(T)/2023/TBHH-TCTBĐATHH MB

1. Khu vực nạo vét: Đoạn Hà Nam, Bạch Đằng luồng hàng hải Hải Phòng (từ phao HP29 đến phao S1).
2. Người hàng hải được khuyến cáo tăng cường cảnh giới khi hành hải qua khu vực này.
3. Các hải đồ sẽ được cập nhật khi công trình hoàn thành.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

Hải đồ ảnh hưởng - VN50008