

09(T)/2018 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.

Source: Viet Nam Maritime Safety - North Notice No. 10/TBHH-TCTBĐATHH MB

**Chart affected - VN50007 (Edition number 2, Edition date December 01st, 2017)
- VN40001 (Edition number 3, Edition date December 01st, 2017)**

1. West cardinal buoy has been temporarily established in the position 20°47.53'N, 106°55.02'E
2. The Lateral buoy, *Fl.R.3s*, has been temporarily adjusted from the position 20°47.81'N, 106°54.82'E to 20°47.78'N, 106°54.78'E

(All positions are referred to WGS84 Datum)

09(T)/2018 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 10/TBHH-TCTBĐATHH MB

**Hải đồ ảnh hưởng -VN50007 (Phiên bản 2, ngày 01 tháng 12 năm 2017)
-VN40001 (Phiên bản 3, ngày 01 tháng 12 năm 2017)**

1. Phao báo hiệu an toàn phía Tây được thiết lập tạm thời tại vị trí 20°47.53'N, 106°55.02'E
2. Phao luồng, *Fl.R.3s*, được điều chỉnh tạm thời từ vị trí 20°47.81'N, 106°54.82'E đến 20°47.78'N, 106°54.78'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)