

40(T)/2022 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.

Source: Viet Nam Maritime Safety - North, Notice No. 87(T)/2022/TBHH-TCTBĐATHHMB

1. The special buoy, $TC, F(3+1)Y.15s$, has been temporarily established in the position $20^{\circ}48.75'N, 106^{\circ}50.21'E$.
2. The lateral buoy, $NT18, FLR.3s$, has been temporarily removed from the position $20^{\circ}48.68'N, 106^{\circ}50.25'E$ to $20^{\circ}48.59'N, 106^{\circ}50.29'E$.
3. Mariners are advised to navigate with caution in the area.

(All positions are referred to WGS84 Datum)

Chart affected - VN50008

40(T)/2022 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 87(T)/2022/TBHH-TCTBĐATHHMB

1. Phao báo hiệu đặc biệt, $TC, F(3+1)Y.15s$, được thiết lập tạm thời tại vị trí $20^{\circ}48.75'N, 106^{\circ}50.21'E$.
2. Phao luồng, $NT18, FLR.3s$, được di chuyển tạm thời từ vị trí $20^{\circ}48.68'N, 106^{\circ}50.25'E$ đến $20^{\circ}48.59'N, 106^{\circ}50.29'E$.
3. Người hàng hải được khuyến cáo tăng cường cảnh giới khi hành hải qua khu vực này.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

Hải đồ ảnh hưởng - VN50008