

199(T)/2017 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.

Source: Viet Nam Maritime Safety - North Notice No. 246/TBHH-TCTBĐATHH MB
277/TBHH-TCTBĐATHH MB
279/TBHH-TCTBĐATHH MB
288/TBHH-TCTBĐATHH MB

Chart affected - VN50007 (Edition number 1, Edition date April 16th, 2015)

1. Special Buoys have been temporarily established in the following positions:

<i>Designation</i>	<i>Characteristic</i>	<i>Position</i>
BH2	Fl(3+1)Y.12s	20°53.24'N 106°45.30'E
BH3	Fl(3+1)Y.12s	20°56.67'N 106°46.02'E
H17	Fl(3+1)Y.12s	20°43.29'N 106°57.96'E
H25	Fl(3+1)Y.12s	20°45.12'N 106°55.93'E
H26	Fl(3+1)Y.12s	20°44.42'N 106°56.47'E
H27	Fl(3+1)Y.12s	20°43.72'N 106°57.02'E
H28	Fl(3+1)Y.12s	20°43.02'N 106°57.56'E
H19	Fl(3+1)Y.12s	20°44.71'N 106°56.89'E
TC-J1	Fl(3+1)Y.12s	20°49.63'N 106°48.82'E
TC-J2	Fl(3+1)Y.12s	20°49.63'N 106°48.74'E

2. Former Notice 02(T)/2016 is cancelled.

(All positions are referred to WGS84 Datum)

199(T)/2017 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 246/TBHH-TCTBĐATHH MB
277/TBHH-TCTBĐATHH MB
279/TBHH-TCTBĐATHH MB
288/TBHH-TCTBĐATHH MB

Hải đồ ảnh hưởng - VN50007 (Phiên bản 1, ngày 16 tháng 4 năm 2015)

1. Các phao báo hiệu đặc biệt được thiết lập tạm thời tại những vị trí như sau:

<i>Tên</i>	<i>Đặc tính</i>	<i>Vị trí</i>
BH2	Fl(3+1)Y.12s	20°53.24'N 106°45.30'E
BH3	Fl(3+1)Y.12s	20°56.67'N 106°46.02'E
H17	Fl(3+1)Y.12s	20°43.29'N 106°57.96'E
H25	Fl(3+1)Y.12s	20°45.12'N 106°55.93'E
H26	Fl(3+1)Y.12s	20°44.42'N 106°56.47'E
H27	Fl(3+1)Y.12s	20°43.72'N 106°57.02'E
H28	Fl(3+1)Y.12s	20°43.02'N 106°57.56'E
H19	Fl(3+1)Y.12s	20°44.71'N 106°56.89'E
TC-J1	Fl(3+1)Y.12s	20°49.63'N 106°48.82'E
TC-J2	Fl(3+1)Y.12s	20°49.63'N 106°48.74'E

2. Thông báo cũ 02(T)/2016 bị hủy bỏ.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)