

89(T)/2016 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.

Source: Viet Nam Maritime Safety - North Notice No. 143/TBHH-TCTBĐATHH MB

Chart affected - VN50008 (Edition number 1, Edition date April 16th, 2015)

The following light-buoys and special buoys have been temporarily adjusted position:

<i>Designation</i>	<i>Characteristic</i>	<i>New Position</i>		<i>Old Position</i>	
TC3	Fl(3+1)Y.12s	20°50.94'N	106°45.88'E	20°50.94'N	106°45.87'E
TC5	Fl(3+1)Y.12s	20°50.79'N	106°45.87'E	20°50.77'N	106°45.86'E
TC6	Fl(3+1)Y.12s	20°50.79'N	106°46.04'E	20°50.82'N	106°45.98'E

(All positions are referred to WGS84 Datum)

89(T)/2016 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 143/TBHH-TCTBĐATHH MB

Hải đồ ảnh hưởng -VN50008 (Phiên bản 1, ngày 16 tháng 4 năm 2015)

Các phao luồng và phao đặc biệt dưới đây được tạm thời điều chỉnh vị trí:

<i>Tên</i>	<i>Đặc tính</i>	<i>Vị trí mới</i>		<i>Vị trí cũ</i>	
TC3	Fl(3+1)Y.12s	20°50.94'N	106°45.88'E	20°50.94'N	106°45.87'E
TC5	Fl(3+1)Y.12s	20°50.79'N	106°45.87'E	20°50.77'N	106°45.86'E
TC6	Fl(3+1)Y.12s	20°50.79'N	106°46.04'E	20°50.82'N	106°45.98'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)