

197(T)/2017 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.

Source: Viet Nam Maritime Safety - North Notice No. 261/TBHH-TCTBĐATHH MB

Chart affected - VN50007 (Edition number 1, Edition date April 16th, 2015)

1. The Lateral buoy, *Fl.R.3s*, in position 20°47.53'N, 106°54.89'E is temporarily out of service.
2. The Lateral buoy has been temporarily removed from the position 20°47.00'N, 106°55.20'E to 20°47.09'N, 106°55.13'E.
3. Former Notice 172(T)/2016 is cancelled.

(All positions are referred to WGS84 Datum)

197(T)/2017 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 261/TBHH-TCTBĐATHH MB

Hải đồ ảnh hưởng -VN50007 (Phiên bản 1, ngày 16 tháng 4 năm 2015)

1. Phao luồng, *Fl.R.3s*, ở vị trí 20°47'32.1N, 106°54'53.2E tạm ngừng hoạt động.
2. Phao luồng được di chuyển tạm thời từ vị trí 20°47.00'N, 106°55.20'E đến 20°47.09'N, 106°55.13'E.
3. Thông báo cũ 172(T)/2016 bị hủy bỏ.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)