

38(T)/2017 VIET NAM - SOUTH CENTRAL COAST - DA NANG - Buoyage.

Source: Viet Nam Maritime Safety - North Notice No. 62/TBHH-TCTBĐATHH MB
Chart affected - VN50021 (Edition number 2, Edition date Dec 01st, 2015)

Special Buoys have been temporarily established in the following positions:

<i>Designation</i>	<i>Characteristic</i>	<i>Position</i>
X1	Fl(3+1)Y.12s	16°07.31'N 108°12.53'E
X2	Fl(3+1).Y.12s	16°07.20'N 108°12.74'E

(All positions are referred to WGS84 Datum)

38(T)/2017 VIỆT NAM - BỜ BIỂN NAM TRUNG BỘ - ĐÀ NẴNG - Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 62/TBHH-TCTBĐATHH MB
Hải đồ ảnh hưởng - VN50021 (Phiên bản 2, ngày 01 tháng 12 năm 2015)

Các phao báo hiệu đặc biệt được thiết lập tạm thời tại những vị trí như sau:

<i>Tên</i>	<i>Đặc tính</i>	<i>Vị trí</i>
X1	Fl(3+1)Y.12s	16°07.31'N 108°12.53'E
X2	Fl(3+1).Y.12s	16°07.20'N 108°12.74'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)