

**138(T)/2020 VIET NAM - NORTH EAST COAST - HAI PHONG - Beacons.**

Source: Viet Nam Maritime Safety - North, Notice No. 246(T)/2020/TBHH-TCTBĐATHHMB  
259(T)/2020/TBHH-TCTBĐATHHMB

Two beacons,  $Q(6)+LFl.15s$ , in positions  $20^{\circ}50.28'N$ ,  $106^{\circ}47.30'E$  and  $20^{\circ}50.08'N$ ,  $106^{\circ}49.03'E$  are temporarily out of service.

(All position are referred to WGS84 Datum)

**Chart affected - VN50008**

**138(T)/2020 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Đăng tiêu.**

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 246(T)/2020/TBHH-TCTBĐATHHMB  
259(T)/2020/TBHH-TCTBĐATHHMB

Hai đăng tiêu,  $Q(6)+LFl.15s$ , ở các vị trí  $20^{\circ}50.28'N$ ,  $106^{\circ}47.30'E$  và  $20^{\circ}50.08'N$ ,  $106^{\circ}49.03'E$  tạm ngừng hoạt động.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

**Hải đồ ảnh hưởng - VN50008**