

**59(T)/2017 VIET NAM - NORTH CENTRAL COAST - THANH HOA - NGHI SON - Buoyage.**

Source: Viet Nam Maritime Safety - North Notice No. 89/TBHH-TCTBĐATHH MB

**Chart affected - VN50012 (Edition number 1, Edition date April 16<sup>th</sup>, 2015)**

Special Buoys have been temporarily established in the following positions:

<i>Designation</i>	<i>Characteristic</i>	<i>Position</i>
M1	Fl(3+1)Y.12s	19°22.13'N 105°47.85'E
M2	Fl(3+1)Y.12s	19°22.22'N 105°48.10'E
M3	Fl(3+1)Y.12s	19°22.29'N 105°48.29'E
M4	Fl(3+1)Y.12s	19°22.34'N 105°48.44'E

(All positions are referred to WGS84 Datum)

**59(T)/2017 VIỆT NAM - BỜ BIỂN BẮC TRUNG BỘ - THANH HÓA - NGHI SƠN - Phao.**

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 89/TBHH-TCTBĐATHH MB

**Hải đồ ảnh hưởng - VN50012 (Phiên bản 1, ngày 16 tháng 4 năm 2015)**

Các phao báo hiệu đặc biệt được thiết lập tạm thời tại những vị trí như sau:

<i>Tên</i>	<i>Đặc tính</i>	<i>Vị trí</i>
M1	Fl(3+1)Y.12s	19°22.13'N 105°47.85'E
M2	Fl(3+1)Y.12s	19°22.22'N 105°48.10'E
M3	Fl(3+1)Y.12s	19°22.29'N 105°48.29'E
M4	Fl(3+1)Y.12s	19°22.34'N 105°48.44'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)