

11(T)/2019 VIET NAM - NORTH CENTRAL COAST - HA TINH - VUNG ANG - Buoyage.

Source: Viet Nam Maritime Safety - North, Notice No.11(T)/2019/TBHH-TCTBDATHH MB

The lateral buoy, *Fl.G.3s*, in position 18°07.52'N, 106°23.06'E is temporarily out of service.

The special buoy, *Q(9)15s*, in position 18°06.73'N, 106°23.46'E is temporarily out of service.

The special buoy, *VQ.1s*, in position 18°06.41'N, 106°23.21'E is temporarily out of service.

(All positions are referred to WGS84 Datum)

Chart affected - VN40015

11(T)/2019 VIỆT NAM - BỜ BIỂN BẮC TRUNG BỘ - HÀ TĨNH - VŨNG ÁNG - Phao.

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 11(T)/2019/TBHH-TCTBDATHH MB

Phao luồng, *Fl.G.3s*, ở vị trí 18°07.52'N, 106°23.06'E tạm ngừng hoạt động.

Phao đặc biệt, *Q(9)15s*, ở vị trí 18°06.73'N, 106°23.46'E tạm ngừng hoạt động.

Phao đặc biệt, *VQ.1s*, ở vị trí 18°06.41'N, 106°23.21'E tạm ngừng hoạt động.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

Hải đồ ảnh hưởng - VN40015