

**260(T)/2019 VIET NAM - SOUTH CENTRAL COAST - QUANG NGAI - DUNG QUAT - Buoyage.**

Source: Viet Nam Maritime Safety - North, Notice No.346(T)/2019/TBHH-TCTBĐATHHMB

The Light buoy, *Mo(A)6s*, in position (15°26.23'N, 108°45.38'E) is temporarily out of service.

Lateral buoy, *Fl.R.3s*, in position 15°25.67'N, 108°46.13'E is temporarily out of service.

(All positions are referred to WGS84 Datum)

**Chart affected - VN50023**

**260(T)/2019 VIỆT NAM - BỜ BIỂN NAM TRUNG BỘ - QUẢNG NGÃI - DUNG QUẤT - Hệ thống phao.**

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 346(T)/2019/TBHH-TCTBĐATHHMB

Đèn báo hiệu của phao, *Mo(A)6s*, ở vị trí (15°26.23'N, 108°45.38'E) tạm ngừng hoạt động.

Phao luồng, *Fl.R.3s*, ở vị trí 15°25.67'N, 108°46.13'E tạm ngừng hoạt động.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

**Hải đồ ảnh hưởng - VN50023**