

**222(T)/2020 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.**

Source: Viet Nam Maritime Safety - North, Notice No. 441(T)/2020/TBHH-TCTBĐATHHMB  
446(T)/2020/TBHH-TCTBĐATHHMB

1. The lateral buoy, *Fl.G.3s*, has been temporarily removed from the position 20°49.94'N, 106°47.45'E to 20°49.93'N, 106°47.50'E.
2. The lateral buoy, *Fl.R.3s*, has been temporarily removed from the position 20°49.11'N, 106°53.35'E to 20°49.11'N, 106°53.23'E.

(All positions are referred to WGS84 Datum)

**Chart affected - VN50008**

**222(T)/2020 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Hệ thống phao.**

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 441(T)/2020/TBHH-TCTBĐATHHMB  
446(T)/2020/TBHH-TCTBĐATHHMB

1. Phao luồng, *Fl.G.3s*, được di chuyển tạm thời từ vị trí 20°49.94'N, 106°47.45'E đến 20°49.93'N, 106°47.50'E.
2. Phao luồng, *Fl.R.3s*, được di chuyển tạm thời từ vị trí 20°49.11'N, 106°53.35'E đến 20°49.11'N, 106°53.23'E.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

**Hải đồ ảnh hưởng - VN50008**