

**59(T)/2023 VIET NAM - SOUTH CENTRAL COAST - DA NANG - Buoyage.**

Source: Viet Nam Maritime Safety - North, Notice No.165(T)/2023/TBHH-TCTBĐATHHMB

Special buoys have been temporarily established in the following position:

<i>Designation</i>	<i>Characteristic</i>	<i>Position</i>
P1	F(4)Y.12s	16°09.53'N 108°12.40'E
P2	F(4)Y.12s	16°09.20'N 108°12.87'E
P3	F(4)Y.12s	16°08.75'N 108°12.50'E
P4	F(4)Y.12s	16°09.07'N 108°12.05'E

(All positions are referred to WGS84 Datum)

**Charts affected - VN50021  
- VN30012**

**59(T)/2023 VIỆT NAM - BỜ BIỂN NAM TRUNG BỘ - ĐÀ NẴNG - Hệ thống phao.**

Nguồn: Tổng công ty Bảo đảm an toàn hàng hải miền Bắc, Thông báo số 165(T)/2023/TBHH-TCTBĐATHHMB

Các phao báo hiệu đặc biệt được thiết lập tạm thời tại vị trí như sau:

<i>Tên</i>	<i>Đặc tính</i>	<i>Vị trí</i>
P1	F(4)Y.12s	16°09.53'N 108°12.40'E
P2	F(4)Y.12s	16°09.20'N 108°12.87'E
P3	F(4)Y.12s	16°08.75'N 108°12.50'E
P4	F(4)Y.12s	16°09.07'N 108°12.05'E

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

**Các hải đồ ảnh hưởng - VN50021  
- VN30012**